



9 November 2020

Legal Assistance Centre
P.O.Box 604
Oshakati
NAMIBIA
Tel: +264 81 2604816

Business Connexion Namibia (Pty) Ltd
130 Jan Jonker Road
Windhoek, Namibia
P O Box 6702, Windhoek, Namibia
T +264 61 204 0000
www.bcx.com.na


Dear: Ms Noeske

This letter serves to inform you that the equipment mentioned below has been inspected. The power button board, flexi cable and DC-In cable are faulty and was caused by liquid that spilled on it

REF No. / NWD No.	311458		
Item	Laptop		
Make	Hewlett Packard		
Model	Probook 450 G5		
Serial No.	5CD8523S43		
Cost of Repair	N\$ 4 352.73		
Spares Available	Yes	<input checked="" type="checkbox"/>	No

PLEASE NOTE: Quote rejection fee of N\$287.50 (Including VAT) will be charged

Should you have any further questions please do not hesitate to contact the undersigned.

pp. 
(Bunhilde)

* **Ellen Koepp**
Logistic Manager
Head: Repair Centre
T +264 61 204 0190
F +264 61 235 697
E Ellen.Koepp@bcx.com.na



P. O. Box 6702, Ausspannplatz, Windhoek, Namibia
T +264 61 204 0000 | F +264 61 204 0009 | bcx.com.na

Business Connexion Namibia (Pty) Ltd. Reg N° 89/291 | Directors: RM Mbetjiha (Chairman); J. Nandago; F. Graupe (MD); E. van Staden;; J. van den Handel*
* South African